


Wiring diagram Kawasaki 750/800 sxi



Automatic power down mode.
Power down current draw is 0.0005Amp.
Power supply switch is not necessary.

CDI have to be placed inside sealed e-box to prevent flooding and possible damage of CDI unit.