




WIRING DIAGRAM PDCI-31



COLOUR CODES:

B - black
 Br - brown
 L - blue
 LL - light blue
 G - green
 R - red
 W - white
 Gr - gray
 V - violet
 P - pink
 O - orange