




WIRING DIAGRAM

PDCIS-MX11T



TECHNICAL DATA

- minimum revs	200 RPM
- maximum revs	20000 RPM
- minimum supply voltage	8 Volts
- maximum supply voltage	17 Volts
- recommended power supply voltage	12 ÷ 15 Volts
- max stand-by current draw	30 mAmp
- current draw at 1200 RPM	0.15 Amp
- max current draw without power jet, or GPO engaged	1.1 Amp
- output energy at 11000 RPM	54 mJ
- output energy at 15000 RPM	40 mJ
- output energy at 20000 RPM	30 mJ

COLOUR CODES:

- B - black
- Br - brown
- L - blue
- LL - light blue
- G - green
- R - red
- W - white
- Gr - gray
- V - violet
- P - pink
- O - orange
- Y - yellow