

ZeelProg SOFTWARE INSTALLATION GUIDE

CD content:

- driver (USB programmer driver)
- NET Framework
- ZeelProg

ZeelProg software can be installed on Windows XP/Vista. "NET Framework 3.5" needs to be installed.

1. Insert CD-ROM and browse content.
2. Install USB programmer driver with running "CDM20600.exe" from CD-ROM "driver" directory.
3. Install ZeelProg software with running "setup ZeelProg.exe" from CD-ROM "ZeelProg" directory.

Install "NET Framework" from CD-ROM "NET Framework" directory, if ZeelProg does not start.